

## SERVICE NOTE

Technical Support Department at the LPGTECH company informs about a service action for TECH ONE drivers (produced before 1 April 2016).

The reason for carrying out the action is a software bug in the version below 84 which has recently been disclosed, and which at extremely unfavourable conditions can cause thermal damage to the final control degrees (specific disappearance of signals controlling injections and power supply).

The fault is 100% due to a malfunctioning resulting from the software. After the driver is updated firmware 84 or higher (available in the GasSetting 2.0.4.62 application and later), the problem does not occur. The website currently has version 85 of the firmware.

**The update is mandatory, it should be made urgently!**