

TECHNICAL NOTE NO. 1/2020

Subject: Update of manufacture process of the driver touch panel (RGB connection)

Due to the optimization of the RGB switch dictated by the operational unstabilities, Technical Department of LPGTECH recommends repair by sending a faulty switch to LPGTECH Service Department for processor replacement. The unstable operation of the switch is result from a processor manufacturing defect and repair involves replacement to new one free from defects.

Unstable operation manifests by spontaneous color settings change while driving.

The batch switches from January 2020 are free from defects.

If you have questions please contact the Technical Support Department

e-mail: help@lpgtech.pl

tel.: +48 508 459 299

+48 502 447 473